


MKS 50-400



- 1 = ground
- 2 = signal
- 3 = +5V

50 kPa@0,5V
400 kPa@4,5V

400 kPa = 3 bar
boost pressure

