

MKS50-600 Pressure sensor

Absolute pressure
50-600 kPa

Pin layout:

- 1 = ground
- 2 = signal
- 3 = +5V

